

Inspection Photos

Operator: Rim Operating
API: 067-06515
Date: 2/8/2021



Photo 1. View of the project area from the northern edge facing center.



Photo 2. View of the western project from the northwestern corner facing southward. Revegetation is progressing with mixed grasses such as smooth brome and western wheatgrass.



Photo 3. View of the northern fill slope from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland, with understory of sagebrush, snakeweed, and James galleta.