

Inspection Photos
Operator: Catamount
API: 067-05412
Date: 2/8/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project from the northeastern corner facing southward. Revegetation is progressing in portions with mixed grasses such as western wheatgrass in a dormant vegetative condition.



Photos 3/4. View of Russian thistles blown off of the western project area, and other Russian thistle debris within the project area.



Photo 4. View of the reference area comprised of sagebrush shrubland with understory of grasses and forbs such as western wheatgrass, sand dropped, and James galleta.