

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/16/2021

Submitted Date:

02/16/2021

Document Number:

700702304

FIELD INSPECTION FORM

Loc ID 424796	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10531 Name of Operator: GRIZZLY OPERATING LLC Address: 5847 SAN FELIPE #3000 City: HOUSTON State: TX Zip: 77057				Findings: 22 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424800	WELL	PR	06/13/2012	GW	045-20942	EPPERLY 23A-23-692	PR
424802	WELL	PR	07/19/2012	GW	045-20943	EPPERLY 13D-23-692	PR
424803	WELL	PR	07/26/2012	GW	045-20944	EPPERLY 14B-23-692	PR
424807	WELL	PR	07/19/2012	GW	045-20945	EPPERLY 13C-23-692	PR
424808	WELL	PR	07/26/2012	GW	045-20946	EPPERLY 24D-23-692	PR
424809	WELL	PR	07/19/2012	GW	045-20947	EPPERLY 13A-23-692	PR
424810	WELL	PR	06/13/2012	GW	045-20948	EPPERLY 23B-23-692	PR
424811	WELL	PR	07/23/2012	GW	045-20949	EPPERLY 23D-23-692	PR
424813	WELL	PR	06/13/2012	GW	045-20950	EPPERLY 23C-23-692	PR
424815	WELL	PR	07/10/2012	GW	045-20951	EPPERLY 13B-23-692	PR
424816	WELL	PR	07/26/2012	GW	045-20952	EPPERLY 24B-23-692	PR
424932	WELL	PR	07/26/2012	GW	045-20979	Epperly 14D-23-692	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 2/16/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Epperly 13B, at Location # 424796 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. This location is within a Density Habitat and Wildlife Management Area. Limited storm water inspection due to snow cover.

During this inspection the following possible compliance issues were observed:

1. Location still shows signs of lack of stabilization from previous inspection on pad

2. No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	snow covered/ not plowed		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Signage is located at tank battery		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR				
Comment:					
Corrective Action:				Date:	

Equipment:					corrective date
Type: Bird Protectors	# 12				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 14				
Comment:	All meters calibrated on location within a year.				
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 12				
Comment:	Braden heads have a port for manual gauge monitoring				
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	chemical tanks at well heads				
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 12				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 12				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	500 BBLS	HEATED STEEL AST		,	
Comment:	Two (2) tanks are NOT heated					
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Ramsey, Scott

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	424800	Type:	WELL	API Number:	045-20942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424802	Type:	WELL	API Number:	045-20943	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424803	Type:	WELL	API Number:	045-20944	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424807	Type:	WELL	API Number:	045-20945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424808	Type:	WELL	API Number:	045-20946	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424809	Type:	WELL	API Number:	045-20947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424810	Type:	WELL	API Number:	045-20948	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	424811	Type:	WELL	API Number:	045-20949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	424813	Type:	WELL	API Number:	045-20950	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	424815	Type:	WELL	API Number:	045-20951	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	424816	Type:	WELL	API Number:	045-20952	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	424932	Type:	WELL	API Number:	045-20979	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: This location is within a Density Habitat and Wildlife Management Area.
 Limited storm water inspection due to snow cover.
 1. Location still shows signs of lack of stabilization from previous inspection on pad
 2. No evidence of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 03/23/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702309	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5353198