

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2021

Submitted Date:

02/11/2021

Document Number:

696202317**FIELD INSPECTION FORM**Loc ID 382974 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 100 CHEVRON ROAD

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Patterson, Chris		spwu@chevron.com	All Inspections per Olson
Olson, Andrew		andrewolson@chevron.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210924	WELL	DA	10/01/1990	DA	045-06682	CHEVRON SHALE W11-34	RI
382974	LOCATION	CL			-	CHEVRON SHALE-66S98W 34SWNW	RI

General Comment:

On 2/8/2021, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at Chevron USA's Chevron Shale W11-34 location in Garfield County, Colorado.

This inspection is a followup to #696201596 to document compliance with the following corrective actions: 1002.f

This inspection is also in response to Resolution #402481193 stating "CA Completed"

It was observed in this inspection that the Location remains out of compliance with Rule 1002.f and the corrective action.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	210924	Type:	WELL	API Number:	045-06682	Status:	DA	Insp. Status:	RI
Facility ID:	382974	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696201596 observed that stormwater and erosion control measures have not been installed in accordance with good engineering practices. Operator was required to comply with Rule 1002.f.(2)C by 8/18/2020.

It was observed in this inspection that the wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices. Channelized erosion has continued on southern areas of the Location; BMPs to stabilize the soils and manage runoff have not been installed per good engineering, remain missing or are insufficient/inadequate.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 08/18/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402598477	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5350840
696202318	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5350838