

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2021

Submitted Date:

02/12/2021

Document Number:

700405315

**FIELD INSPECTION FORM**

Loc ID 314843 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 100 CHEVRON ROAD  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email            | Comment |
|----------------|-------|------------------|---------|
| Sanford, Anita |       | atlx@chevron.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 229729      | WELL | PR     | 11/01/2019  | OW         | 103-07386 | UPRR (RE-ENTRY)<br>73X-29 | PR          |

**General Comment:**

A routine inspection identified the following compliance issues:

- 1) Mud tracked from access road shared by many wells unto Hwy 64. This inspection is linked to the nearest well to Hwy 64 that uses the access road. Photos 1, 2, 3, 4. Complete by 3-14-2020.

This is a summary of inspection report 700405315.

**Inspected Facilities**

Facility ID: 229729 Type: WELL API Number: 103-07386 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Mud tracked from access road shared by many wells unto Hwy 64. The road junction is across from the paved road that leads to the warehouse & CO2 plant.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 03/14/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402599164    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351469</a> |
| 700405316    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351460">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351460</a> |