

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2021

Submitted Date:

02/11/2021

Document Number:

700702282

**FIELD INSPECTION FORM**

Loc ID 335386 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: GRIZZLY OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		sgghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276751	WELL	PR	04/02/2008	GW	045-10521	FERGUSON 34B-27-692	PR
276753	WELL	PR	10/10/2005	GW	045-10522	FERGUSON 44D-27-692	PR
276756	WELL	PR	06/01/2013	GW	045-10523	FERGUSON 44B-27-692	PR
276759	WELL	PR	04/02/2008	GW	045-10524	FERGUSON 34D-27-692	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Monday 2/11/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Ferguson, at Location # 335386 in Garfield county Colorado.  
While there, I observed normal production operations. All meters calibrated on location within a year. Some of the C/A's from previous inspection document # 700702022 have NOT been completed. This location is within a Density Habitat and Wildlife Management Area.

During this inspection the following possible compliance issues were observed:  
1. Location still shows signs of lack of stabilization from previous inspection on pad  
2. No evidence of tracking control BMP's  
Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Signage is located at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	200 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 276751 Type: WELL API Number: 045-10521 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 276753 Type: WELL API Number: 045-10522 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 276756 Type: WELL API Number: 045-10523 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

Facility ID: 276759 Type: WELL API Number: 045-10524 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms		Ditches				

Comment: This location is within a Density Habitat and Wildlife Management Area.  
 1. Location still shows signs of lack of stabilization from previous inspection on pad  
 2. No evidence of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location  
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 01/14/2021

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402599274	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351640">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351640</a>
700702291	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351631</a>