

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/09/2021

Submitted Date:

02/12/2021

Document Number:

700702287

**FIELD INSPECTION FORM**

Loc ID 335500 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: GRIZZLY OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293185	WELL	PR	09/18/2008	GW	045-14918	SCHIRER 13C-26-692	PR
293186	WELL	PR	09/21/2008	GW	045-14919	SCHIRER 13B-26-692	PR
293190	WELL	PR	09/15/2008	GW	045-14920	SCHIRER 13A-26-692	PR
293192	WELL	PR	09/24/2008	GW	045-14921	SCHIRER 14B-26-692	PR
293193	WELL	PR	11/12/2008	GW	045-14922	SCHIRER 14C-26-692	PR
293196	WELL	PR	09/20/2008	GW	045-14923	SCHIRER 14D-26-692	PR
293200	WELL	PR	09/23/2008	GW	045-14917	SCHIRER 13D-26-692	PR

**General Comment:**

COGCC Inspection Report Summary  
On Tuesday 2/9/2021 at approximately 1400, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Schirer, at Location # 335500 in Garfield county Colorado.  
While there, I observed normal production operations. All meters calibrated on location within a year. Some of the C/A's from previous inspection document # 700702017 have NOT been completed. This location is within a Density Habitat and Wildlife Management Area.  
  
During this inspection the following possible compliance issues were observed:  
1. Location still shows signs of lack of stabilization from previous inspection on pad  
2. No evidence of tracking control BMP's  
Refer to photograph of observed compliance issue.  
  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Signage is located at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at well heads		
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 7		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	HEATED STEEL AST		,
Comment:	375 BBL tanks and one (1) tank is NOT heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293185	Type:	WELL	API Number:	045-14918	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293186	Type:	WELL	API Number:	045-14919	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293190	Type:	WELL	API Number:	045-14920	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293192	Type:	WELL	API Number:	045-14921	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293193	Type:	WELL	API Number:	045-14922	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293196	Type:	WELL	API Number:	045-14923	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	293200	Type:	WELL	API Number:	045-14917	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps		Ditches				
Ditches						
Rip Rap						
Berms		Culverts				

Comment: This location is within a Density Habitat and Wildlife Management Area  
 1. Location still shows signs of lack of stabilization from previous inspection on pad  
 2. No evidence of tracking control BMP's

Corrective Action: 1. Install or repair required BMPs in order to achieve stabilization on location  
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 01/13/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402599278	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351644">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351644</a>
700702295	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351635</a>