

Inspection Photos  
Operator: Hilcorp Energy  
API: 067-06266  
Date: 2/11/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope facing northward. Trailers, wood piles, fencing materials, etc. remain stored on the western and northwestern portions of the project area.



Photo 3. View of the reference area comprised of irrigated grass fields and sagebrush/pinyon/juniper mosaic.



Photos 4/5. View of closed gates after leaving location.