

Inspection Photos

2/17/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 1: Photo taken from the south end of the Location, facing north. Photo provides an overview of the Location. Photo also show vehicle tracking/rutting issues observed on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 2: Photo taken from the south end of the Location, facing northeast. Photo provides an overview of the Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 3: Photo taken from the west end of the Locaiton, facing north. Photo shows tracking/rutting on the location; BMPs to stabilize pad missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



20210217

Photo 4: See comments under photo 3.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 5: Photo taken from the south end of the Location, facing south. Photo of sediment trap.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567




Photo 6: Photo taken from the east end of the Location, facing east. Photo shows areas of the slope where erosion degradation is evident. Photo also shows the hay bale control measure on the perimeter of the Location is in disrepair. Location adjacent to an intermittent drainage along the eastern perimeter.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 7: Photo taken from the northeast end of the Location, facing north. Photo shows separator equipment and cut slopes. BMPs missing or insufficient to manage run-on, and stabilize/protect the cut slope; sediment observed falling from cut slopes during inspection.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 8: Photo taken from the north end of the Location, facing west. Photo shows cut slope has been constructed with a steep slope and that BMPs to manage run-on, and to stabilize/protect the cut slope are missing or insufficient.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 9: Photo of the cut slope. See comments under photo 7



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 10: Photo of the cut slope. See comments under photo 7



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 11: Photo taken from the northwest corner of the Location, facing east. Photo shows cut slope has been constructed with a steep slope and that BMPs to manage run-on, and to stabilize/protect the cut slope are missing or insufficient.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 12: Photo taken from the northwest corner of the Location, facing south. Photo provides an overview of the production area, and interim areas. Visible vegetation predominantly desirable perennial plant species.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 13: Photo taken from the west end of the Location, facing southwest. Photo shows interim areas and ditch along the west end of the Location/slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 14: Continued from photo 13. Photo shows ditch has not been constructed in accordance with good engineering practices; stormwater incision within the ditch evident.