

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



Battery sign missing Operator name.

Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**



**Location shows signs of lack of stabilization BMP's
in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



Sediment build up behind falling rock guard rails.

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



**N39.55096 W108.12064 Rut damage in ditch.
Water not draining off road into culvert or ditch.**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



**Access road shows signs of lack of stabilization
BMP's in some areas (rutting is present).**



**N39.55348 W-108.11985 Erosion damage
from culvert outlet.**

**CAERUS PICEANCE LLC
CHEVRON-66S96W 4SWNW
Location # 335578**



**N39.55348 W-108.11985 Erosion damage
from culvert outlet.**