

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/17/2021

Document Number:

700405424

FIELD INSPECTION FORM

 Loc ID 315628 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10654
 Name of Operator: LASSO OIL & GAS LLC
 Address: 3021 RIDGE RD #156
 City: ROCKWALL State: TX Zip: 75032
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Boulger, Levin		lboulger@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231188	WELL	PR	03/09/1995	GW	103-08857	DIAMOND-SHAMROCK-FEDERAL 1-5	PR

General Comment:

A follow up inspection of FIR documents:

- 1) 700404749 dated 12-23-2020.
- 2) 700405379 dated 2-8-2021.

The following compliance issues are uncompleted:

- 1) Report past due monthly operations on Form 7. Complete by 1-11-2021.
- 2) Calibrate gas meter. Photo 7. Complete by 2-1-2021.
- 3) Missing "911" on well sign. Photo 8. Complete by 2-1-2021.
- 4) Gas leak at well wheel valve. Photos 3, 4. Complete by 2-1-2021.

The emergency number 800-209-9762 was called on 2-17-2021 @ 3:20p to report the gas leak again.

Well is located on BLM land, black bear area, a Rule 1202.d mule deer migration corridor area, and a Rule 1202.d mule deer winter concentration area.

This is a summary of inspection report 700405424.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: "911" missing on well sign.

Corrective Action: Add "911" to the sign.

Date: 02/01/2021

Overall Good:

Spills:

Type	Area	Volume	
------	------	--------	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Gas Meter Run	# 2		
Comment:	Most recent meter calibration in June 2019 in the meter building still in use.		
Corrective Action:	Meters need calibrated annually.	Date:	02/01/2021
Bradenhead	# 1		
Comment:	Bradenhead access.		
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 231188 Type: WELL API Number: 103-08857 Status: PR Insp. Status: PR

Producing Well

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production May 2020.

Audiable flow in meter building. Tubing pressure 40 psi. No casing gage present.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 02/01/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: 3" of snow on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

