

**Inspection Photos**  
**Location Name: Cosslet A 9 Flowline**  
**Spill ID: 478542**



**Photo 1 – Spill excavation area. Fencing is down around open excavation.**



**Photo 2 – 3<sup>rd</sup> party lines running through open excavation.**





**Inspection Photos**  
**Location Name: Cosslet A 9 Flowline**  
**Spill ID: 478542**



**Photo 3 – Free product present in open excavation.**



**Photo 4 – Free product present in open excavation.**





**Inspection Photos**  
**Location Name: Cosslet A 9 Flowline**  
**Spill ID: 478542**



**Photo 5 – Soils stored on site.**



**Photo 6 – Soils stored on site.**





**Inspection Photos**  
**Location Name: Cosslet A 9 Flowline**  
**Spill ID: 478542**



**Photo 7 – Weeds/debris in open excavation**



**Photo 8 – Weeds/debris in open excavation**

