

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2021

Submitted Date:

02/24/2021

Document Number:

699103204**FIELD INSPECTION FORM**
 Loc ID 432677 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Petrie, Erica		erica.petrie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432676	WELL	PR	08/01/2020	OW	123-37227	State Antelope U-Y-32HNB	PR
432754	WELL	PR	11/01/2019	OW	123-37267	State Antelope P-T-32HNB	SI
436243	WELL	PR	08/01/2020	OW	123-39003	STATE ANTELOPE P41-T44-32HNC	PR
436244	WELL	PR	08/01/2020	OW	123-39004	State Antelope 41-44-32HNB	PR
436826	WELL	PR	08/01/2020	OW	123-39279	STATE ANTELOPE U41-Y44-32HNC	PR

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Pumping Unit, see attached photos.		
Corrective Action:	Comply with Rule 603.f.		Date: 03/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 432676 Type: WELL API Number: 123-37227 Status: PR Insp. Status: PR

Producing WellComment: Pr

Corrective Action:

Date:

Facility ID: 432754 Type: WELL API Number: 123-37267 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Facility ID: 436243 Type: WELL API Number: 123-39003 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 436244 Type: WELL API Number: 123-39004 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 436826 Type: WELL API Number: 123-39279 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
On Wednesday 2/24/21 at approximately 1059hrs, I, Inspector Adam Burns,
Conducted an on-site inspection to prior inspection document #696301565 at State
Antelope P-32 Pad of Bonanza Creek Energy, at
Location ID # 432677 in Weld County, Colorado.
During this inspection the CA for the riser has not been corrected
Unmarked Riser at Pumping Unit, see attached photos.
Comply with Rule 603.f. With a corrective action date of 3/17/20.
See attached photos.
This is a summary of inspection report.

burnsa

02/24/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103205	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360568