

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2021

Submitted Date:

02/24/2021

Document Number:

699103200**FIELD INSPECTION FORM**Loc ID 462929 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
462928	WELL	DG	02/23/2021		123-49889	State Seventy Holes 11-14-8HNB	DG

**General Comment:**[Surface Casing being drilled at the time of inspection.](#)

**Inspected Facilities**

Facility ID: 462928 Type: WELL API Number: 123-49889 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Ensign 161 Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: \_\_\_\_\_

**Comment:** Surface casing being drilled. Drilling head, 1620' TD at the time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
COGCC Inspection Report Summary On Wednesday 2/24/21 at approximately 0937hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Seventy Holes J-5 pad of Bonanza Creek Energy Location ID: 462929 in Weld County, Colorado. While there, I observed surface drilling operations by Ensign 161 drilling at 1620', Drilling head on the State Seventy Holes 11-14-8 HNB API: 05-123-49889. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.	burnsa	02/24/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103201	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360566</a>