

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2974 from entrance to location.




Photo #2975 Rutting present on location due to lack of stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2976 Rutting present on location due to lack of stabilization.



Photo #2977 Rutting present on location due to lack of stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2978 No form of tracking control at the entrance to location.



Photo #2979 No form of tracking control at the entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2980 Sediment has been plowed into ditch and is choking off vegetation.



Photo #2981 Sediment has been plowed into ditch and is choking off vegetation.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2982 Sediment has been plowed into ditch and is choking off vegetation.



Photo #2983 Battlement habitat restoration area.