

# Inspection Photos

Operator: Hilcorp Energy  
API: 067-09409  
Date: 2/24/2021



Photo 1. View of the well pad entrance facing center.



Photo 2. View of the southern project area facing westward. Dense weed debris observed along the fenceline of the working area.





Photo 3. View of the western project area facing southward. Dense weed debris observed along the fencelines.