

Inspection Photos

API: 099-06354

Operator: BERRY* WALTER V DBA BERRY
ENERGY INC

Inspection Date: 2/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 1. Facing northeast toward the location. There are soil pile that remain from the pits at the northeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 2. Facing southeast at the location. Vegetation has re-established. An outline of the location remains where it was graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 3. Facing east at the location. The pits have not been backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 4. Facing west at the opposite side of the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 5. Facing southwest toward the pit berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 6. This pit remains at the north side of the location. Pit liner debris remains in the pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021

Inspection Photos



Photo 7. Facing southwest toward the two open pits that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06354 | Date: 2/23/2021