

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2021

Submitted Date:

02/22/2021

Document Number:

696202348

## FIELD INSPECTION FORM

 Loc ID: 314804  
 Inspector Name: Trujillo, Aaron  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 OGCC Operator Number: 16700  
 Name of Operator: CHEVRON USA INC  
 Address: 100 CHEVRON ROAD  
 City: RANGELY State: CO Zip: 81648
**Contact Information:**

Contact Name	Phone	Email	Comment
Patterson, Chris		spwu@chevron.com	All Inspections per Olson
Olson, Andrew		andrewolson@chevron.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229626	WELL	SI	06/18/1998	ERIW	103-07283	CARNEY C T 24X35	RI
314804	LOCATION	AC			-	CARNEY C T-62N102W 35NWNE	RI

**General Comment:**

On 2/19/2021, Reclamation Specialist Trujillo conducted a stormwater inspection at Chevrons USA Inc's CARNEY C T #24X35 location in Rio Blanco County, Colorado.

The following compliance issues were observed during this inspection:

1002.f.: Stormwater Management  
606: Good Housekeeping

Refer to the "Good Housekeeping" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type: TRASH

Comment:

Corrective Action:

Date: 03/22/2021

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 229626 Type: WELL API Number: 103-07283 Status: SI Insp. Status: RI

Facility ID: 314804 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed that stormwater and erosion control measures to protect the slopes, and to allow for sediment laden-free stormwater discharge are missing, or insufficient; Runoff causing gulley erosion on the northeast corner of the Location; slopes along western end of the Location bare/exposed; degradation evident.

Corrective Action: Comply with Rule 1002.f.(2)C and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition.

Date: 03/22/2021

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402607050	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5357921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5357921</a>
696202349	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5357913">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5357913</a>