

Inspection Photos
Operator: Simcoe
API: 067-06959
Date: 3/1/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing with native and non-native grasses such as western wheatgrass, crested wheatgrass, and smooth brome, as well as shrubby rubber rabbitbrush.



Photo 3. View of the southern project area facing eastward. Fencing is damaged and no longer functioning in many places, needing repair. Loose strands of barbed wire can be entrap wildlife.



Photo 4. View of the reference area comprised of sagebrush shrubland with understory of grasses and forbs such as purple three awn, western wheatgrass, and mat penstemon.