

Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 324199

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 1: Photo taken from the north end of the Location, facing southeast. Photo provides an overview of the Location. Photo also shows rutting and tracking issues observed on the Location; pad not sufficiently stabilized.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 2: Photo taken from the north end of the Location, facing southwest. Photo provides an overview of the Location. Photo also shows rutting and tracking issues observed on the Location; pad not sufficiently stabilized.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 3: Photo of sign at battery

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 4: Photo taken from the west end of the Location, facing southwest. Desirable perennial vegetative establishment observed on cut slopes.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 5: Photo shows anchor on the southeast end of the Location. Anchor(s) not marked in accordance with Rule 1003.a and 603.j

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 6: Photo taken from the interim areas. Photo shows vegetation from previous years growing season is predominantly undesirable weedy plant species such as cheat grass.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 7: Photo taken from the west end of the Location, facing east. Photo shows erosion degradation due to stormwater runoff from the Location. Stormwater and erosion control measure missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324199



Photo 8: Photo taken from the west end of the Location, facing west. Photo shows erosion degradation due to stormwater runoff from the Location. Stormwater and erosion control measure missing or insufficient.