

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2021

Submitted Date:

03/02/2021

Document Number:

696302982

**FIELD INSPECTION FORM**

Loc ID 427181 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96155  
Name of Operator: WHITING OIL & GAS CORPORATION  
Address: 1700 LINCOLN STREET SUITE 4700  
City: DENVER State: CO Zip: 80290

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment                             |
|--------------|-------|------------------------------|-------------------------------------|
| ,            |       | WhitingEasternCO@Whiting.com | <a href="#">Eastern Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 427180      | WELL | PR     | 11/01/2013  | OW         | 123-34888 | Wildhorse 02-0224H | PR          |

**General Comment:**

This is a Field Inspection ONLY. Any corrective action(s) from previous Interim Reclamation and Stormwater Inspection #682504554 dated 02.28.2019 that have not been addressed are still applicable.

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | Adequate             |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |                                      |       |            |
|--------------------|--------------------------------------|-------|------------|
| Type               | UNUSED EQUIPMENT                     |       |            |
| Comment:           | Unused Tank on location. See photos. |       |            |
| Corrective Action: | Remove Tank to comply with Rule 606  | Date: | 05/03/2021 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |

**Equipment:**

|                               |                                  |       |                 |
|-------------------------------|----------------------------------|-------|-----------------|
| Type: Pump Jack               | # 1                              |       | corrective date |
| Comment:                      |                                  |       |                 |
| Corrective Action:            |                                  | Date: |                 |
| Type: Emission Control Device | # 1                              |       |                 |
| Comment:                      |                                  |       |                 |
| Corrective Action:            |                                  | Date: |                 |
| Type: Bradenhead              | # 1                              |       |                 |
| Comment:                      | Appears to be plumbed to surface |       |                 |
| Corrective Action:            |                                  | Date: |                 |

|                               |     |  |       |
|-------------------------------|-----|--|-------|
| Type: Gas Meter Run           | # 1 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Vertical Separator      | # 1 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Vertical Heater Treater | # 1 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |
| Type: Flare                   | # 1 |  |       |
| Comment:                      |     |  |       |
| Corrective Action:            |     |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 1 | 400 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| Metal              | Adequate                             | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 3 | 400 BBLs | STEEL AST |         | 40.786424,-103.948350 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Metal    | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |             |       |
|--------------------|-------------|-------|
| Type               | Field Flare |       |
| Comment:           |             |       |
| Corrective Action: |             | Date: |

**Inspected Facilities**

Facility ID: 427180 Type: WELL API Number: 123-34888 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Routine Field Inspection. Unused Tank on Location.</a> | petrie | 03/02/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696302983    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365339">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365339</a> |