

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/24/2021

Submitted Date:

02/24/2021

Document Number:

699103204

**FIELD INSPECTION FORM**
 Loc ID 432677 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Petrie, Erica		erica.petrie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432676	WELL	PR	08/01/2020	OW	123-37227	State Antelope U-Y-32HNB	PR
432754	WELL	PR	11/01/2019	OW	123-37267	State Antelope P-T-32HNB	SI
436243	WELL	PR	08/01/2020	OW	123-39003	STATE ANTELOPE P41-T44-32HNC	PR
436244	WELL	PR	08/01/2020	OW	123-39004	State Antelope 41-44-32HNB	PR
436826	WELL	PR	08/01/2020	OW	123-39279	STATE ANTELOPE U41-Y44-32HNC	PR

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser at Pumping Unit, see attached photos.		
Corrective Action:	Comply with Rule 603.f.		Date: 03/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 432676 Type: WELL API Number: 123-37227 Status: PR Insp. Status: PR

**Producing Well**Comment: Pr

Corrective Action:

Date:

Facility ID: 432754 Type: WELL API Number: 123-37267 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 436243 Type: WELL API Number: 123-39003 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 436244 Type: WELL API Number: 123-39004 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 436826 Type: WELL API Number: 123-39279 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary  
On Wednesday 2/24/21 at approximately 1059hrs, I, Inspector Adam Burns,  
Conducted an on-site inspection to prior inspection document #696301565 at State  
Antelope P-32 Pad of Bonanza Creek Energy, at  
Location ID # 432677 in Weld County, Colorado.  
During this inspection the CA for the riser has not been corrected  
Unmarked Riser at Pumping Unit, see attached photos.  
Comply with Rule 603.f. With a corrective action date of 3/17/20.  
See attached photos.  
This is a summary of inspection report.

burnsa

02/24/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402609889	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360570">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360570</a>
699103205	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360568</a>