

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2021

Submitted Date:

03/03/2021

Document Number:

700702383

**FIELD INSPECTION FORM**

Loc ID: 334893    Inspector Name: Ramsey, Scott    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**  
 OGCC Operator Number: 10456  
 Name of Operator: CAERUS PICEANCE LLC  
 Address: 1001 17TH STREET #1600  
 City: DENVER    State: CO    Zip: 80202

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 12 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262978	WELL	PR	10/31/2002	GW	045-08087	HMU 10-7 (F10W)	PR
262979	WELL	PR	11/12/2002	GW	045-08088	HMU 10-12(F10W)	PR
262980	WELL	PR	02/01/2008	GW	045-08089	HMU 10-6 (F10W)	PR
262981	WELL	PR	06/16/2005	GW	045-08090	HMU 10-7 (F10)	PR
262982	WELL	PR	05/10/2009	GW	045-08091	HMU 10-11 (F10W)	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Wednesday 3/3/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus F10, at Location # 334893 in Garfield county Colorado.  
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within a CPW Density/High Priority Habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.  
 During this inspection the following possible compliance issues were observed:  
 1. Tank battery signage does not meet requirements of new rule 605.e  
 2. Location shows signs of lack of stabilization on pad  
 3. Access road needs maintained (lack of compaction)  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access road needs maintained (lack of compaction) See stormwater C/A		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	1. Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 10		corrective date
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>262978</u>	Type:	<u>WELL</u>	API Number:	<u>045-08087</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>262979</u>	Type:	<u>WELL</u>	API Number:	<u>045-08088</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>262980</u>	Type:	<u>WELL</u>	API Number:	<u>045-08089</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>262981</u>	Type:	<u>WELL</u>	API Number:	<u>045-08090</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>262982</u>	Type:	<u>WELL</u>	API Number:	<u>045-08091</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Culverts				
Compaction	Fail	Ditches				
Berms		Compaction	Fail			

Comment: This location is within a CPW Density/High Priority Habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.  
 1. Location shows signs of lack of stabilization on pad  
 2. Access road needs maintained (lack of compaction)

Corrective Action: **Install or repair required BMPs**

Date: 05/03/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702387	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5366433">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5366433</a>