

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Tote northeast of compressor need placards due to them being weathered "Sign not legible. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	03/16/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in several locations needs to be removed, for good housekeeping. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	03/16/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	03/16/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Automation/ Totes		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	1 is a buy back station/ 1 is a sales gas meter.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Leak appears to be coming from compressor causing an oily skid.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	03/16/2021
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Risers are not LO/TO or Marked in multiple spots. See attached photos.		
Corrective Action:	Comply with Rule 1102.o.	Date:	03/16/2021
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER					
Comment:	Gaslift skid				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment: Berm around gaslift skid is weathered. See attached photos.					
Corrective Action: Maintain secondary containment devices to comply with 603.o.				Date: 03/16/2021	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		
Comment: Shares containment with crude oil tanks.					
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		
Comment: Shares containment with crude oil tanks.					
Corrective Action:				Date:	
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)	60 BBL				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLs	STEEL AST		40.363600,-104.414200
Comment:					
Corrective Action:				Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:

Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 429919 Type: WELL API Number: 123-35968 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/13/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Well needs updated annual bradenhead test on file. Submit reports.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 3/4/21 at approximately 0741hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte P-T-34HZ Pad of Bonanza Creek Energy, at Location ID # 429920 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused Equipment in multiple locations, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 3/16/21. Berm around gaslift skid is weathered. Maintain secondary containment devices to comply with 603.o. With a corrective action date of 3/16/21. Tote northeast of compressor need placards due to them being weathered "Sign not legible". Install sign to comply with Rule 605.h. With a corrective action date of 3/16/21. Stained soil in several locations needs to be removed, for good housekeeping. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 3/16/21. Risers are not LO/TO or Marked in multiple spots. Comply with Rule 1102.o. With a corrective action date of 3/16/21 Leak appears to be coming from compressor causing an oily skid. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 3/16/21 Well needs updated annual bradenhead test on file. Submit reports. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	03/04/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103225	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5367714