

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2021

Submitted Date:

02/25/2021

Document Number:

699802659**FIELD INSPECTION FORM**Loc ID 334525 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289143	WELL	PR	04/08/2015	GW	077-09237	RED MOUNTAIN RANCH 33-11	PR
289144	WELL	PR	02/08/2008	GW	077-09236	RED MOUNTAIN RANCH 33-13	PR
289145	WELL	PR	10/01/2020	GW	077-09235	RED MOUNTAIN RANCH 4 -2	PR
289146	WELL	PR	10/03/2007	GW	077-09234	RED MOUNTAIN RANCH 33-14	PR
289147	WELL	PR	02/08/2008	GW	077-09233	RED MOUNTAIN RANCH 33-15	PR

**General Comment:****COGCC Inspection Report Summary**

On Thursday 2/25/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at LARAMIE ENERGY LLC Red Mountain Ranch /33-11 Pad, Location #334525 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Wellhead sign weathered and not legible. See photo #2986 with a corrective action date of 3/25/21. Flow line heating insulation open ended and not capped. See photo #2987 with a corrective action date of 3/25/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	Note there is no battery sign located at the battery. The previous information was posted at the entrance to location and does not meet the new battery sign requirements of Rule 605 e.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Wellhead sign weathered and not legible. See photo #2986			
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.			Date: 03/25/2021
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Barded wire fence around location			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Horizontal Heated Separator	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 4			

Comment:	No form of pressure monitoring located on braden heads. All braden head valves are accessible.				
Corrective Action:				Date:	
Type: Other		# 3			
Comment:	Flow line heating insulation open ended and not capped. See photo #2987				
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.			Date:	03/25/2021
Type: Vertical Heated Separator		# 4			
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run		# 4			
Comment:	All meter runs have been calibrated in the last year.				
Corrective Action:				Date:	
Type: Bird Protectors		# 2			
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift		# 4			
Comment:	All wells on plunger lift				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 289143 Type: WELL API Number: 077-09237 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 289144 Type: WELL API Number: 077-09236 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well has been PA

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 289145 Type: WELL API Number: 077-09235 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 289146 Type: WELL API Number: 077-09234 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 289147 Type: WELL API Number: 077-09233 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Gravel				
Ditches						
		Berms				
		Drains				
		Culverts				
Berms						

Comment: Limited storm water inspection due to location being covered with snow. The location appears to have been plowed with the confines of the location BMP's.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Refer to Equipment and Signs/Marker for corrective actions.	depaoloc	02/25/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402611927	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5362589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5362589</a>
699802660	Photos for Insp. #699802659	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5362581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5362581</a>