

Inspection Photos

API: 009-06453

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06453 | Date: 3/3/2021

Inspection Photos



Photo 1. Facing northeast toward the well site. The location has not been reclaimed. Equipment and debris remains at the location. All equipment should have been removed within 3 months of abandoning the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 3/3/2021

Inspection Photos



Photo 2. Equipment and debris remains at the location. All equipment should have been removed within 3 months of abandoning the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 3/3/2021

Inspection Photos



Photo 3. Facing northwest at the location. A tank battery remains at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 3/3/2021

Inspection Photos



Photo 4. Facing northeast toward the pit. The pit liner is torn and degraded. There is various debris in the pit. The pit was never closed and reclaimed as required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06453 | Date: 3/3/2021