

Caerus Piceance LLC
J17
Location # 334872

Mar 1, 2021 at 10:57:21 AM
39.444582,-107.687081 ±4.87m
COGCC



Location entrance

Mar 1, 2021 at 10:57:03 AM
39.444477,-107.687047 ±5.49m
COGCC



Looking north on CR 315 by entrance

Caerus Piceance LLC
J17
Location # 334872

Mar 1, 2021 at 11:03:23 AM
39.444686,-107.686279 ±4.84m
COGCC



Location/ debris

Mar 1, 2021 at 10:57:38 AM
39.444675,-107.687103 ±4.85m
COGCC



location entrance

Caerus Piceance LLC
J17
Location # 334872



Previous inspection photo of equipment stored on pad surface



Follow up inspection photo of equipment still stored on pad surface


Caerus Piceance LLC
J17
Location # 334872

Mar 1, 2021 at 10:59:24 AM
39.444780,-107.686618 ±4.80m
COGCC



Random debris

Mar 1, 2021 at 10:59:43 AM
39.444780,-107.686618 ±4.80m
COGCC



Random debris



Caerus Piceance LLC
J17
Location # 334872



Random debris



Random debris (ESD tank float)

Caerus Piceance LLC
J17
Location # 334872



Random debris



Random debris

Caerus Piceance LLC
J17
Location # 334872



Random debris



Random debris

Caerus Piceance LLC
J17
Location # 334872



Random debris



Random debris

Caerus Piceance LLC
J17
Location # 334872



Previous inspection photo of soil storage on location



Follow up inspection photo of soil storage on location

Caerus Piceance LLC
J17
Location # 334872



Previous inspection photo of material storage on pad surface



Follow up inspection photo of material storage on pad surface

Caerus Piceance LLC
J17
Location # 334872

Mar 1, 2021 at 11:00:54 AM
39.444820,-107.686104 ±4.94m
COGCC



Mar 1, 2021 at 11:01:30 AM
39.444896,-107.686043 ±4.91m
COGCC



Follow up inspection photo of material storage on pad surface / BMP's are failing

Caerus Piceance LLC
J17
Location # 334872



Previous inspection of manway open



Follow up inspection of manway is sealed but still
no secondary containment

