

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2021

Submitted Date:

03/05/2021

Document Number:

699802717

FIELD INSPECTION FORM

Loc ID 334759 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278065	WELL	SI	03/01/2020	GW	045-10836	DAYBREAK FEDERAL 30-2BB (PB30)	SI

General Comment:

COGCC Inspection Report Summary
On Friday 3/5/21 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30NWNE, Location #334759 in Garfield County Colorado.
While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed: Rutting present on location due to lack of stabilization. See photo #3072 and #3073. No form of tracking control. See photo #3074 with a corrective action date of 3/20/21. Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Type	BATTERY			
Comment:	Note there is no battery sign located at the battery. The previous information was posted on the tanks and does not meet the new battery sign requirements of Rule 605 e.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Wellhead signs located at separators and not wellheads.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	_____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:				
Corrective Action:			Date:	
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire fence around location			
Corrective Action:			Date:	
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:	Summit midstream			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.			

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Centralized containment	
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 278065 Type: WELL API Number: 045-10836 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Ditches						
		Berms				
		Culverts				
Other	Fail					no form of tracking control.
		Gravel				
Berms						
		Ditches				
		Sediment Traps				
Compaction	Fail					Rutting present on location

Comment: Rutting present on location due to lack of stabilization. See photo #3072 and #3073. No form of tracking control. See photo #3074 Location is located in a high priority habitat area.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 03/20/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to stormwater for corrective actions.	depaoloc	03/05/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802718	Photos for Insp. #699802717	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5369286