

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2021

Submitted Date:

02/28/2021

Document Number:

688309828

FIELD INSPECTION FORM

Loc ID 414280 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10722
Name of Operator: KTM OPERATING LLC
Address: 1246 BAYOU LACARPE ROAD
City: HOUMA State: LA Zip: 70360

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Kosola, Jason		jason.kosola@state.co.us	
Burn, Diana		diana.burn@state.co.us	
James, Cole	719-892-0378	cj0378@hotmail.com	Pumper

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414278	WELL	IJ	07/10/2015	DSPW	073-06391	CRAIG 6-4 SWD	SI

General Comment:

[Reinspection](#)

No production data submitted to COGCC database since Jun 2018.
Submit required Form 7(s) to COGCC per Rule 309. Contact COGCC Engineering. Date: 09/20/2019

[Repair metal tank berms that have rusted and leaked produced water.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	Adequate	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: same metal berms as produced water tanks				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	FIBERGLASS AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	Adequate	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Comment:	During spill (see inspection #700600237), produced water ran under and through berms (see attached photos of rusted metal berms). Repair metal berms and provide adequate secondary containment to prevent leaks.	
Corrective Action:	Inadequate berms around tank(s).	Date: 03/16/2021

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 414278 Type: WELL API Number: 073-06391 Status: IJ Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: ABCK

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 02/23/2018

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: No production/disposal data submitted to COGCC database since Jun 2018.

Corrective Action: Submit required Form 7(s) to COGCC per Rule 309. Contact COGCC Engineering. Date: 09/20/2019

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI for spill (see Inspection #700600247)

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402614012	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5364427
688309829	KTM Operating Craig 6-4 SWD SPILL	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5364424