

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2021

Submitted Date:

03/03/2021

Document Number:

696202406

**FIELD INSPECTION FORM**Loc ID 335811 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275162	WELL	PR	09/01/2020	GW	045-13473	CHEVRON 41A-8D	RI
275238	WELL	PR	09/01/2020	GW	045-13494	CHEVRON 44D-5D	RI
335811	LOCATION	AC			-	CHEVRON-66S96W 4SWSW	RI

**General Comment:**

On 3/1/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Caerus Piceance's UNOCAL-66S96W /4SWSW location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:  
606.a: Equipment, Weeds, Waste and Trash Requirements.

Refer to the "Good Housekeeping" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>What appears to be an unused cattle guard is being stored adjacent to the access road, at the location entrance. See photo #1.</p> <p>Since Location entrance and access road is shared/utilized by two Operators (Caerus and Berry Petroleum), corrective action to remove unused equipment is being provided to both Operators.</p>		
Corrective Action:	Comply with Rule 606.a	Date:	03/18/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	275162	Type:	WELL	API Number:	045-13473	Status:	PR	Insp. Status:	RI
<b>Producing Well</b>									
Comment:	PR Well, IR and SW inspection.								
Corrective Action:						Date:			
Facility ID:	275238	Type:	WELL	API Number:	045-13494	Status:	PR	Insp. Status:	RI
<b>Producing Well</b>									
Comment:	PR Well, IR and SW inspection.								
Corrective Action:						Date:			
Facility ID:	335811	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

No waste and debris observed on the production and interim areas.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

See good housekeeping.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

No anchors observed on the Location.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
---------------------------------------	---

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

  

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____	
Debris removed _____	No disturbance /Location never built _____	
Access Roads _____	Regraded _____	Contoured _____
		Culverts removed _____
	Gravel removed _____	
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____	
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____
Weeds present _____	Subsidence _____	

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%	_____
TRANSECT RESULTS OF REFERENCE AREA%	_____
TOTAL % OF DESIRABLE VEGETATION COVER	_____
VEGETATIVE COVER	_____

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					East end of pad
Compaction	In Process	Compaction	In Process			
Gravel	In Process	Gravel	In Process			

Comment: BMPs to stabilize pad during wet conditions showing signs of degradation and disrepair; off-location sediment transport not observed at time of inspection, however pad stabilization and tracking issues becoming evident.

Maintainence is advised; ensure control measures to stabilize pad and mitigate off location sediment transport are maintained in proper functioning condition in accordance with good engineering practices, pursuant to Rule 1002.f

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402616120	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365949</a>