

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2021

Submitted Date:

03/03/2021

Document Number:

696202411

FIELD INSPECTION FORM

Loc ID 335566 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		COGCC.inspections@caerus oilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284331	WELL	PR	03/01/2019	GW	045-12149	CHEVRON 1N-4D	RI
284332	WELL	PR	03/01/2019	GW	045-12148	CHEVRON 8I-5D	RI
284333	WELL	PR	03/01/2019	GW	045-12147	CHEVRON 8K-5D	RI
284334	WELL	PR	03/01/2019	GW	045-12146	CHEVRON 8L-5D	RI
335566	LOCATION	AC			-	CHEVRON-66S96W 4SWSW	AC

General Comment:

On 3/1/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Caerus Piceance??s CHEVRON-66S96W 4SWSW location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:
1002.f: Stormwater.

Refer to the "Reclamation" and "stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	284331	Type:	WELL	API Number:	045-12149	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR Well, IR and SW inspection.								
Corrective Action:						Date:			
Facility ID:	284332	Type:	WELL	API Number:	045-12148	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR Well, IR and SW inspection.								
Corrective Action:						Date:			
Facility ID:	284333	Type:	WELL	API Number:	045-12147	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR Well, IR and SW inspection.								
Corrective Action:						Date:			
Facility ID:	284334	Type:	WELL	API Number:	045-12146	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR Well, IR and SW inspection.								
Corrective Action:						Date:			
Facility ID:	335566	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

No waste and debris observed on production and interim areas.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

No unused or unneeded equipment observed on production and interim areas.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Anchors observed marked pursuant to Rule 1003.a.

Corrective Action _____

Date _____

1003b. Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Fail</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? <u>Fail</u>	Segregated soils have been replaced? <u>Pass</u>
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	
Top soil replaced <u>Pass</u>	Recontoured <u>Pass</u> 80% Revegetation <u>In</u>
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? _____	
Comment	Though there are areas on the south end of the pad that don't appear to be needed for production, the pad has been reasonably reduced. Interim areas appear to be progressing towards COGCC 1003 standards; desirable perennial vegetative establishment evident though undesirable weedy plant species such as cheat grass is prevalent throughout the interim areas. Evidence of heavy grazing pressure on interim areas also observed and may hinder reclamation progression.
Corrective Action	
Overall Interim Reclamation	In Process
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: _____	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment:	

Corrective Action: _____						Date: _____
Overall Final Reclamation _____		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:	It was observed in this inspection that stormwater and erosion control measures to stabilize production area and prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition; rutting and tracking issues observed.	Date: 03/18/2021
Corrective Action:	Comply with Rule 1002.f and implement required stormwater and erosion control measures. Ensure BMPs are adequate for the site's conditions, are installed in accordance with good engineering practices and maintained in proper functioning condition.	

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402616123	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365952
696202412	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5365946