

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2021

Submitted Date:

03/03/2021

Document Number:

700702380

FIELD INSPECTION FORMLoc ID 334921 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264836	WELL	PR	08/06/2003	GW	045-08945	HMU 10-1B (A10WB)	PR
264838	WELL	PR	08/13/2003	GW	045-08948	HMU 10-2B (A10WB)	PR
264839	WELL	PR	08/15/2003	GW	045-08949	HMU 10-2D (A10WB)	PR
264877	WELL	PR	08/02/2003	GW	045-08954	ROSE RANCH 10-8B (A10WB)	PR
265104	WELL	PR	08/15/2003	GW	045-08946	HMU 3-15D (A10WB)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 3/3/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus A10WB, at Location # 334921 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within a CPW Density/High Priority Habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e
 2. Location shows signs of lack of stabilization on pad
 3. Sediment from pad is being moved off of location with snow removal
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	muddy in areas		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	1. Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	970-285-2615/ 911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	All meters have been calibrated on location within the past year.		

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	shared containment with 500 BBL tanks				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	in tank battery containment				
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:	shared containment with 300 BBL condensate tank					
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 264836 Type: WELL API Number: 045-08945 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 264838 Type: WELL API Number: 045-08948 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 264839 Type: WELL API Number: 045-08949 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 264877 Type: WELL API Number: 045-08954 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 265104 Type: WELL API Number: 045-08946 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
Compaction	Fail					
Sediment Traps		Ditches				
Berms		Culverts				

Comment: This location is within a CPW Density/High Priority Habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.
 1. Location shows signs of lack of stabilization on pad
 2. Sediment from pad is being moved off of location with snow removal

Corrective Action: **Install or repair required BMPs**

Date: 04/05/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402616797	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5366434
700702384	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5366430