

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2021

Submitted Date:

03/10/2021

Document Number:

701002525

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
303350 \_\_\_\_\_ Welsh, Brian \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 25255  
Name of Operator: DUKE GAS COMPANY LLC  
Address: 22500 COUNTY RD 24  
City: VERNON State: CO Zip: 80755

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Cantrall, Diana		djcantrall@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252951	WELL	PR	06/01/2017	GW	125-06828	CANTRALL 2-35	DM

**General Comment:**

Routine Inspection

*(This area is intentionally left blank for additional notes or observations.)*

Location			
<b>Lease Road:</b>			
	Type	Access	
	comment:	Dirt road through farm ground	
	Corrective Action:		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type	OTHER	
	Comment:	Lease sign for Cantrall 2-35 by meter shed	
	Corrective Action:		Date:
<b>Emergency Contact Number:</b>			
	Comment:	<input style="width: 50%;" type="text"/>	
	Corrective Action:	<input style="width: 50%;" type="text"/>	Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
	Comment:	<input style="width: 80%;" type="text"/>	
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead and gas scrubber	
	Corrective Action:		Date:
<b>Equipment:</b>			
Type:	Ancillary equipment	# 2	corrective date
	Comment:	Gas scrubber at wellhead (for domestic use). Telemetry equipment at meter shed	
	Corrective Action:		Date:
Type:	Vertical Separator	# 4	
	Comment:	3-Vertical gas separators 50% buried by meter shed for the Cantrall 35-1, 35-7, 35-8 1-Vertical gas separator 50% buried by meter shed abandoned and not in use (for Cantrall 2-35)	
	Corrective Action:		Date:
Type:	Gas Meter Run	# 3	
	Comment:	Shared meter run for (Cantrall 35-1, 35-7, 35-8) 240' north of wellhead	
	Corrective Action:		Date:
<b>Venting:</b>			
	Yes/No		
	Comment:		
	Corrective Action:		Date:
<b>Flaring:</b>			

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 252951 Type: WELL API Number: 125-06828 Status: PR Insp. Status: DM

**Producing Well**

Comment: Well is converted to domestic well for farmhouse and producing. Meter run is removed at meter shed and VGS is still in place at meter shed. Central meter run for (Cantrall 35-1, 35-7, 35-8) 240' N of wellhead

Corrective Action: Submit Sundry notice for current well status (DM)

Date: 04/08/2021

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701002550	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372375">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372375</a>