

Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335970

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



20210309

Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



Photo 5: Photo of signs at location entrance.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



20210309

Photo 6: Photo of 80 bbl tank on Location. Signage peeling off. Inspection #701100324 observed that the tank is rusted and peeling paint. Inspection required Operator to "Inspect, maintain and repair tanks following standard industry practice such as API 12R" by 11/3/2020. Corrective action from FIR 701100324 does not appear to have been addressed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



Photo 7: Photo shows porta-john on Location is properly secured.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335970



Photo 8: Photo taken from the northern interim areas. Interim areas appear to be progressing towards COGCC 1003 Standards. Photo also shows stormwater run-on ditch and berm installed at interim areas.

