

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2021

Submitted Date:

03/10/2021

Document Number:

688309862

**FIELD INSPECTION FORM**

Loc ID 317103 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10690  
Name of Operator: IMPETRO RESOURCES LLC  
Address: 2820 LOGAN DRIVE  
City: LOVELAND State: CO Zip: 80538

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Bradley, Sam	970-593-8626	sbradley.impetro@gmail.com	Principal Agent
Gibson, Rick	970-768-6880	rtgibson01@msn.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236368	WELL	PR	03/01/2020	OW	121-08858	PIEPER NICHOLS 1	PR

**General Comment:**

Routine Inspection

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	lease sign at CR 38		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

**Equipment:**

Type:			corrective date
Vertical Heater Treater	# 1		
Comment:	shed, berms, propane		
Corrective Action:			Date:
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Prime Mover	# 1		

Comment: <span style="color:blue;">electric</span>		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <span style="color:blue;">same earth berms as produced water tank</span>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)	150 bbls				
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
121-08858

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
------	--	--	--	--

Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 236368 CDP: \_\_\_\_\_

Comment:

Corrective Action:  **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:  **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:  **Date:** \_\_\_\_\_

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 236368 Type: WELL API Number: 121-08858 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR 12/1/2020 production reported to COGCC database.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date: \_\_\_\_\_

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type:      Netting Condition: \_\_\_\_\_

Comment:	
Corrective Action	Date:
Anchor Trench Present: _____ Oil Accumulation: <u>NO</u> 2+ feet Freeboard: <u>NO</u>	
Comment: <u>first pit</u>	
Corrective Action	Date:
Type: <u>Produced Water</u> Lined: <u>NO</u> Pit ID: _____ Lat: _____ Long: _____	
Reference Point: _____ Other: _____ Length: _____ Width: _____	
<b>Lining:</b>	
Liner Type: _____ Liner Condition: _____	
Comment:	
Corrective Action	Date:
<b>Fencing:</b>	
Fencing Type: <u>Livestock</u> Fencing Condition: <u>Adequate</u>	
Comment:	
Corrective Action	Date:
<b>Netting:</b>	
Netting Type: _____ Netting Condition: _____	
Comment:	
Corrective Action	Date:
Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: <u>YES</u>	
Comment: <u>small amount of oil on NW cor of second pit (see attached photo)</u>	
Corrective Action	Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688309940	Impetro Resources Pieper Nichols 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373371">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373371</a>