

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2021

Submitted Date:

03/11/2021

Document Number:

689805466

FIELD INSPECTION FORMLoc ID 324754 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Boyer, David	303-994-0000	david@d90energy.com	
Neidel, Kris		kris.neidel@state.co.us	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296567	WELL	PR	10/01/2020	OW	057-06469	SPICER 3-32H	SI

General Comment:

Routine FIU inspection.

Sandridge signs on location have D90 stickers placed over the name and emergency contact information. Signs have not been updated beyond this. No Form 9 in the database. No evidence of transfer from Sandridge to D90 in database. Inspector received sale letter via email after calling D90 to follow up on sign changes.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. Tank labels should contain: name of operator, operator emergency contact number, tank capacity, tank contents, NFPA label.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/11/2021
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/11/2021
Type	BATTERY		
Comment:	Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/11/2021

Emergency Contact Number:

Comment: 713-227-0391

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	#		

Comment:			
Corrective Action:	Please confirm bradenhead monitoring with telemetry via FIRR.	Date:	04/12/2021
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 296567 Type: WELL API Number: 057-06469 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: No Form 9 in the database. No evidence of transfer from Sandridge to D90 in database.Corrective Action: Submit Form 9 to comply with Rule 218. Date: 03/11/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
Gravel						
Compaction						
		Gravel				

Comment: [Snow cover inhibited scope of stormwater inspection. No apparent soil migration; erosion or soil movement. Full stormwater inspection will be performed after snowmelt.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689805482	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373942