

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2021

Submitted Date:

03/11/2021

Document Number:

692700032

**FIELD INSPECTION FORM**Loc ID 324025 Inspector Name: KELLERBY, SHAUN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Ramsey, Scott		scott.ramsey@state.co.us	
Longworth, Mike		michael.longworth@state.co.us	
De Paolo, Corey		corey.depaulo@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211522	WELL	PR	08/01/2020	GW	045-07282	BENTLEY 11-24	PR

**General Comment:**

Inspection was conducted due to COGCC staff observation of heavy tracking of sediment onto Garfield County road 301.

On 3/9/21, I Shaun Kellerby conducted a field inspection of facility #324025, SENE 11 7S95W, in Garfield County Colorado. I observed normal production operations.

Facility 324025 is located in a designated High Priority Habitat area, and in close proximity to USFWS wetlands inventory area, and rule 1202c NSO habitat area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign not posted or information inaccurate at battery		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	04/16/2021

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211522	Type:	WELL	API Number:	045-07282	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Last reported production 12/20.								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Heavy Tracking onto county road from lease road is occurring. No tracking BMP are present at the time of inspection. Run-on is not controlled, and storm water is allowed to move through location. Sediment migration is ongoing on the north side of location. Storm water from location and the main lease road is directed to the bottom of the lease road where the tracking is occurring.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/19/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692700033	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374404">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374404</a>