

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2021

Submitted Date:

03/12/2021

Document Number:

679603733

FIELD INSPECTION FORMLoc ID 327053 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 88265

Name of Operator: TIGGES OIL LLC

Address: 12406 WCR 64 1/2

City: GREELEY State: CO Zip: 80631

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Tigges, Kenneth	970-396-8381	levi.tigges@gmail.com	
,	970-686-2836	oakleylee@msn.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
56731	WELL	SI	08/01/2020	OW	123-14072	TIGGES 3-31B	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Unable to read sign. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 06/09/2021
Type	TANK LABELS/PLACARDS		
Comment:	One tank does not contain signage. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 06/09/2021
Type	WELLHEAD		
Comment:	Displays different well name. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 06/09/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at pumpjack. See attached photo.		
Corrective Action:	Comply with 608.e.		Date: 06/09/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near pumpjack and tank battery. See attached photos.		
Corrective Action:	comply with Rule 606		Date: 06/09/2021
Type	WEEDS		
Comment:	Weeds inside tank battery berm. See attached photos.		
Corrective Action:	comply with Rule 606		Date: 06/09/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil/water tank				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tank				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Anchored				
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Inadequate berm surrounds tank battery. See attached photos.				
Corrective Action:	Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3).				Date: 06/09/2021
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 56731 Type: WELL API Number: 123-14072 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: siCorrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Tuesday, March 9, 2021 at approximately 1:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at TIGGES 3-31B (Tigges Oil Co. LLC.), at location #: 327053 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. Wrong well name is displayed at pumpjack. Install sign to comply with Rule 605.d. (Corrective Action Date: June 9, 2021) See attached photo #1. 2. It appears to be stained soil at the pumpjack. Remove and comply with Rule 608.e. (Corrective Action Date: June 9, 2021) See attached photo #3, 4. 3. Weeds inside tank battery, unused equipment near pumpjack and tank battery. Remove to comply with Rule 606 (Corrective Action Date: June 9, 2021) See attached photos #5-9. 4. Unlegible tank battery sign/no signage for fiberglass tank in tank battery. Install sign to comply with Rule 605.h. (Corrective Action Date: June 9, 2021) See attached photos #10, 11. 5. Inadequate berm surrounds tank battery. According to COGCC's maps, the location is within floodplains. Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3). (Corrective Action Date: June 9, 2021) see attached photos #12-14. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	03/10/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603738	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374770