

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2021

Submitted Date:

03/12/2021

Document Number:

701101261

**FIELD INSPECTION FORM**Loc ID 335299 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259726	WELL	PR	04/05/2001	GW	045-07775	PA 23-34	PR
265751	WELL	PR	01/08/2003	GW	045-09054	PA 313-34	PR
270390	WELL	PR	05/13/2004	OW	045-09545	PA 523-34	PR
270394	WELL	PR	05/10/2004	GW	045-09546	PA 423-34	PR

**General Comment:****COGCC Inspection Report Summary**

Location is in close proximity of Colorado River and creeks that run to the river in a High Priority Habitat Area. (Mule Deer Winter Concentration Area) 317B External Buffer Zone Inspection

During this inspection the following possible compliance issues were observed:

Weathering well signs are cracking and peeling.

Capacity volumes on tank label is faded and not legible from a distance(100')

Debris on location. See photos

Disturbed area at corner on location and access road(cattle guard) has disturbed drainage bmp of location. Ditch on access before cattle guard needs maintained.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Capacity volumes on tank label is faded and not legible from a distance(100')		
Corrective Action:	"Comply with Rule 605.h. (1).C. Tank capacity; (2) Lettering on all new Tanks, and on any reapplied or modified labels, will be legible from a distance of 100 feet."	Date:	06/13/2021
Type	BATTERY		
Comment:	Weathering sign. Battery sign is not at tank battery.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Weathering well signs are cracking and peeling.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	06/13/2021

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris on location. See photos		
Corrective Action:	Comply with Rule 606	Date:	03/20/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 259726 Type: WELL API Number: 045-07775 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 265751 Type: WELL API Number: 045-09054 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 270390 Type: WELL API Number: 045-09545 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 270394 Type: WELL API Number: 045-09546 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
Drains	Fail					
		Ditches	Fail			
		Culverts				
Berms						
Ditches						

Comment: [Disturbed area at corner on location and access road\(cattle guard\) has disturbed drainage bmp of location. Ditch on access before cattle guard needs maintained.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 03/27/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101262	Inspection 701101261 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375257</a>