



Whiting Oil & Gas Corporation

WILDHORSE 05-0514H CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 427525

Section 5 T9N R59W

3-12-2021



Impacted soils no longer at Wellhead or Exhaust