

Inspection Photos
Operator: Simcoe
API: 067-08843
Date: 3/10/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area facing eastward. Reclamation areas are infested with weeds such as Scotch thistle (approx. 200 individuals) and kochia debris.



Photo 3. View of culvert crossing on access road, appears to be stabilized at this time.



Photo 4. View of the western project area facing northward.



Photo 5. View of reference area comprised of sagebrush and grassland mosaic with grasses such as western wheatgrass and forbs that are dormant at this time.