

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2021

Submitted Date:

03/10/2021

Document Number:

690201259

FIELD INSPECTION FORM

Loc ID 307299 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rmack@ogrisop.com	
		efitzgerald@ogrisop.com	
		timothy.thomsen@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217414	WELL	PR	05/06/2020	GW	071-06191	APACHE CANYON 20-5	RI

General Comment:

This is a follow up of the previous inspection number 690200861.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type			
Comment:	Good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	The steel grates around the wellhead do not completely cover the area around the well. This could be a potential hazard for wildlife entry.		
Corrective Action:	Cover and protect the area around the wellhead to prevent entry.	Date:	03/12/2021
Type	OTHER		
Comment:	There is oil and oily rags in the engine skid that need to be cleaned up.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area.	Date:	03/12/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The cattle guard along the main road is filled in with sediment and is not maintained. There are areas along the main road where stormwater is not diverted toward the culvert which is creating vehicle rutting and pooling on the road. Areas of rutting along the road need to be repaired and properly stabilized. Previous corrective action was not performed. Corrective action needs to be performed immediately to obtain compliance. Additionally, there is vehicle rutting west of the well site where the drip line is located.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/23/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402624840	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372920
690201260	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372910