

Inspection Photos

API: 073-06713

Operator: UNIT PETROLEUM COMPANY

Inspection Date: 3/17/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06713 | Date: 3/17/2021

Inspection Photos



Photo 1. Facing north at the beginning of the access road. The gravel and cattleguard remains and the fence has not been put back to original place. Additional H-brace posts are shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06713 | Date: 3/17/2021

Inspection Photos



Photo 2. There is a gravel pile that remains near the location. The gravel pile needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06713 | Date: 3/17/2021

Inspection Photos



Photo 3. Facing south towards the location. It appears the location has been cross-ripped. The location needs to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06713 | Date: 3/17/2021

Inspection Photos



Photo 4. Facing west towards the location. It appears the location has been cross-rippled. The location needs to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06713 | Date: 3/17/2021

Inspection Photos



Photo 5. Facing southwest toward the undisturbed surrounding reference. There is vegetation planted in the surround crop field.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06713 | Date: 3/17/2021