

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2021

Submitted Date:

03/12/2021

Document Number:

679603733

**FIELD INSPECTION FORM**

Loc ID 327053 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 88265  
Name of Operator: TIGGES OIL LLC  
Address: 12406 WCR 64 1/2  
City: GREELEY State: CO Zip: 80631

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Tigges, Kenneth	970-396-8381	levi.tigges@gmail.com	
,	970-686-2836	oakleylee@msn.com	<a href="#">ALL INSPECTIONS</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
56731	WELL	SI	08/01/2020	OW	123-14072	TIGGES 3-31B	SI

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Displays different well name. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/09/2021
Type	TANK LABELS/PLACARDS		
Comment:	One tank does not contain signage. See attached photo.		
Corrective Action:	Install sign to complu with Rule 605.h.	Date:	06/09/2021
Type	BATTERY		
Comment:	Unable to read sign. See attahed photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/09/2021

<b>Emergency Contact Number:</b>			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at pumpjack. See attached photo.		
Corrective Action:	Comply with 608.e.	Date:	06/09/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near pumpjack and tank battery. See attached photos.		
Corrective Action:	comply with Rule 606	Date:	06/09/2021
Type	WEEDS		
Comment:	Weeds inside tank battery berm. See attached photos.		
Corrective Action:	comply with Rule 606	Date:	06/09/2021

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No  
 Comment:   
 Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:			Date: _____

<b>Equipment:</b>			
Type: Emission Control Device	# 1	corrective date	
Comment:			
Corrective Action:			Date: _____

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil/water tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shares containment with crude oil tank					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment: Anchored					
Corrective Action:				Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment: Inadequate berm surrounds tank battery. See attached photos.					
Corrective Action: Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3).				Date:	06/09/2021
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 56731 Type: WELL API Number: 123-14072 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: si

Corrective Action:  Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary                      **Weather Conditions: cloudy, dry ground                      On Tuesday, March 9, 2021 at approximately 1:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at TIGGES 3-31B (Tiggess Oil Co. LLC.), at location #: 327053 in WELD COUNTY Colorado.                      While there, I observed a shut in facility.                      During this inspection the following possible compliance issues were observed:                      1. Wrong well name is displayed at pumpjack. Install sign to comply with Rule 605.d. (Corrective Action Date: June 9, 2021) See attached photo #1.                      2. It appears to be stained soil at the pumpjack. Remove and comply with Rule 608.e. (Corrective Action Date: June 9, 2021) See attached photo #3, 4.                      3. Weeds inside tank battery, unused equipment near pumpjack and tank battery. Remove to comply with Rule 606 (Corrective Action Date: June 9, 2021) See attached photos #5-9.                      4. Unlegible tank battery sign/no signage for fiberglass tank in tank battery. Install sign to comply with Rule 605.h. (Corrective Action Date: June 9, 2021) See attached photos #10, 11.                      5. Inadequate berm surrounds tank battery. According to COGCC's maps, the location is within floodplains. Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3). (Corrective Action Date: June 9, 2021) see attached photos #12-14.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	03/10/2021

**Attached Documents**  
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402626928	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374775">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374775</a>
679603738	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374770">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374770</a>