



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Flow Line	# 1				
Bradenhead	# 1	Bradenhead valve is exposed at surface.			
Other	# 1	Wellbore is secured with a loose fitting metal cover that does not allow for pressure monitoring. See attached photo.	Comply with Rule 434.a.(5).	03/26/2021	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Location #319626				
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 244341 Type: WELL API Number: 123-12135 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well was plugged beginning December 2020 and into January 2021, waiting on cut/cap and flowline abandonment.

Corrective Action:

Date: \_\_\_\_\_

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>            On Friday 3/12/2021 at approximately 08:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Starck #1 location #322832 in Weld County, Colorado.            While there, I observed that the wellbore is secured with a loose fitting metal cover that does not allow for pressure monitoring. During this inspection the following possible compliance issues were observed: Rule 434.a.(5). with a corrective action date of 3/26/2021.            A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.            This is a summary of the inspection report.</p>	petersont	03/12/2021

**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402627145	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374973">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374973</a>
697003285	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374971</a>