

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/10/2021

Submitted Date:

03/12/2021

Document Number:

701101259

FIELD INSPECTION FORMLoc ID 334912 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256254	WELL	PR	10/13/1999	GW	045-07437	PA 41-6	PR
270605	WELL	PR	02/12/2005	OW	045-09564	PA 341-6	PR
270606	WELL	PR	12/01/2004	OW	045-09565	PA 441-6	PR
270607	WELL	PR	02/14/2005	GW	045-09566	PA 344-31	PR
270627	WELL	PR	02/10/2005	OW	045-09576	PA 541-6	PR

General Comment:**COGCC Inspection Report Summary**

Location is in close proximity of Colorado River and creeks that run to the river in a High Priority Habitat Area. (Mule Deer Winter Concentration Area)

During this inspection the following possible compliance issues were observed:

Deadman marker knocked over.

Location lacks stabilization.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Battery sign is not at tank battery.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 5		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	Deadman marker knocked over.		
Corrective Action:	Repair deadman marker.		Date: 03/27/2021
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities				
Facility ID: <u>256254</u>	Type: <u>WELL</u>	API Number: <u>045-07437</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing well</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>270605</u>	Type: <u>WELL</u>	API Number: <u>045-09564</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing well</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>270606</u>	Type: <u>WELL</u>	API Number: <u>045-09565</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing well</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>270607</u>	Type: <u>WELL</u>	API Number: <u>045-09566</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing well</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>270627</u>	Type: <u>WELL</u>	API Number: <u>045-09576</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing well</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Culverts				
Gravel						
		Ditches				
Seeding						
		Gravel				

Comment: [Location lacks stabilization.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 03/27/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402626847	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374707
701101260	Inspection 701101259 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5374702