

Inspection Photos
Location Name: Dryer 1
Location ID: 306577



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Dryer 1
Location ID: 306577



Photo 3 – Wellhead

Photo 4 – Black Container – Missing Content and NFA Label has faded

Inspection Photos
Location Name: Dryer 1
Location ID: 306577



Photo 5 – Unused Belts

Photo 6 – Inside Engine House