

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP /2-34B

Location ID: 334103



Photo #3202 from entrance to location.



Photo #3204 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP /2-34B

Location ID: 334103



Photo #3205 Location lacks stabilization.



Photo #3206 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC HYRUP /2-34B

Location ID: 334103



Photo #3207 No form of tracking control at entrance to location.