

**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**





**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Storm water run-on from access road.**



**Sediment build up in back corner of fence.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Unmarked deadman over north east edge  
of location.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Unmarked deadman over south east edge  
of location.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Tread protector north east of the east side wells.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Piece of 8" casing on edge of location.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Drains running off location behind wells.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**South drain needs maintained.**



**South drain needs maintained.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**North drain needs maintained.**



**North drain needs maintained.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Rock stock pile in front of west set of wells.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Location lacks stabilization.**



**Location lacks stabilization.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Location lacks stabilization.**



**Location lacks stabilization.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Location lacks stabilization.**



**Location lacks stabilization.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Drillings products from staging drilling rig  
during rig move.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Culvert and ditch need maintained.**



**Culvert needs maintained.  
39.51834 108.13325**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Culvert needs maintained.  
39.51834 108.13325**



**Ditch damaged from traffic.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Location lacks stabilization.**



**Run on storm water from access road.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Culvert needs maintained.  
39.51834 108.13400**



**Culvert needs maintained.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Culvert needs maintained.  
39.51834 108.13400**



**Culvert needs maintained.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Low water cross on access road.  
39.51610 108.13443**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Storm water not flowing effectively.**



**Road is damaged on run off side of low water crossing.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Sediment build up and traffic damage in ditch.**



**No apparent BMPs at entrance of location.**



**TEP ROCKY MOUNTAIN LLC  
CHEVRON-66S96W 20NENW  
Location # 335458**



**Sediment build up and traffic damage in ditch.**



**Sediment build up and traffic damage in ditch.**