

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2021

Submitted Date:

03/15/2021

Document Number:

688309915

FIELD INSPECTION FORMLoc ID 317092 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 14855

Name of Operator: CENTRAL OPERATING INC

Address: 1600 BROADWAY STE 1050

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Staley, Conner	3038949576	coidenverproduction@gmail.com	
Crumley, Luke	(970) 324-0060	crumleypumping@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236129	WELL	SI	09/01/2020	OW	121-08619	MARICK A-2	PR

General Comment:

Reinspection, passed, 3 corrective actions-access road was maintained, stuffing box oil under fencing removed but still oil stained soil under stuffing box, animal holes in berms are back.

Stained soils at wellhead, pit berms on south side are eroding into pasture and down the hill with an erosion rill forming on SE corner of pasture just outside the pit fence. Leaking valve behind (north of) east 200 bbl tank. Remove free oil, removed stained soil inside berms and fix leaking tank valve.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

OTHER

Comment: Leaking valve at east, 200 bbl tank (see attached photos).

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

For localized stained soils or oily waste - Properly dispose of oily waste in accordance with 905.e.

Date: 04/16/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities									
Facility ID:	236129	Type:	WELL	API Number:	121-08619	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	PR 1/1/2021 production reported to COGCC database.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: Pit berms eroding into pasture and rill forming on south side of pit in pasture. Maintain animal holes in tank battery berms.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/16/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date:

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Inspector Name: Sherman, Susan

Corrective		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402628269	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375836
688309967	Central Operating Marick A-2 REIN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375833